



Field Test Report

23.5R25 ECOMEGA M5DLX L5 2**TL



LATEST INSPECTION DATE

03/07/2015


2015

A.O.

Background Info

Customer Reference	CI05718
Country/City	ITALY
Brand/Type	23.5R25
Internal number	ECOMEGA M5DLX
Operation site	GLASS RECYCLING
Machine Producer	VOLVO
Model	L110G
Tires fitting date	09/01/2015
Hours at fitting date	3.862

Machine Type





Field Test Report

23.5R25 ECOMEGA M5DLX L5 2**TL

Test Report

INSPEC DATE	TIRE POS.	HOURS MONT.	HOURS INSPEC.	HOURS RUNNING	ORIG. T.D. (mm)	T.D. INTER N (mm)	T.D. EXTER N (mm)	T.D. AVERAGE (mm)	PROJECTION TO END (hours)	INFL. (bar)
03/07/15	FL	3.862	6.262	2.400	85			0	2.400	525,0
	FR	3.862	6.262	2.400	85			0	2.400	525,0
	RL	3.862	6.262	2.400	85			0	2.400	475,0
	RR	3.862	6.262	2.400	85			0	2.400	475,0

Note

MACHINE WORKS ON GLASS RECYCLING FACTORY
IN 6 MONTHS TIRES RUNNED 2.400 HOURS

FIRST INSPECTION:

CASINGS LOOK VERY NICE AT THE END OF THEIR LIFE
3 SHIFT PER DAY WITH HIGH TEMPERATURE AND STRESSFUL WORK/APPLICATION

Conclusion

CASINGS HAVE BEEN SUCCESSFULLY REMOULDED WITH L5 XMINE PROFILE
CUSTOMER WAS VERY SATIFY AND REPLACED THESE TIRES WITH OTHERS ECOMEGA M5DLX