

Field Test Report

23.5R25 ECOMEGA M5DT L5 2** TL



LATEST INSPECTION DATE

16/06/2015


2015

FIELD
TECHNICIAN

Background Info

Customer Reference	CI00583
Country/City	ITALY/ MILANO
Dimension	23.5R25
Brand/Type	ECOMEGA M5DT
Operation site	WASTE MANAGEMENT SITE
Machine Producer	VOLVO
Model	L120
Tires fitting date	06/06/2014
Hours at fitting date	9.600

Machine Type





Field Test Report

23.5R25 ECOMEGA M5DT L5 2** TL

Test Report

INSPEC DATE	TIRE POS.	HOURS MONT.	HOURS INSPEC.	HOURS RUNNING	ORIG. T.D. (mm)	T.D. INTERN (mm)	T.D. EXTERN (mm)	T.D. AVERAGE (mm)	PROJECTION TO END (km)	INFL. (bar)
22/06/2015	FL	9.600	11.100	1.500	74	56	57	57	6.343	4,5
	FR	9.600	11.100	1.500	74	56	57	57	6.343	4,5
	RL	9.600	11.100	1.500	74	56	57	57	6.343	4
	RR	9.600	11.100	1.500	74	56	57	57	6.343	4

Note

TIRES WERE FITTED BEFORE SUMMER (06/06/2014) TO REPLACE ORIGINAL ONES IN PREMIUM BRANDS. IN 12 MONTHS TIRES RUNNED 1.500 HOURS

FIRST INSPECTION:

TIRES LOOK VERY NICE

AVERAGE WORKED HOURS FOR EACH MM OF TREAD: 88 H

SECOND INSPECTION:



Field Test Report

Conclusion 23.5R25 ECOMEGA M5DT L5 2** TL

Photo report

