

Field Test Report

23.5R25 M3HA+ 2** ECOMEGA E3/L3 TL




LATEST INSPECTION DATE	01/03/2016	2016	T.C.
------------------------	------------	------	------

Background Info

Customer Reference	C106023
Country/City	CENTER ITALY
Brand/Type	
Internal number	
Operation site	WOOD WESTE STATION
Machine Producer	LIEBHERR
Model	L550
Tires fitting date	23/01/2014
Hours at fitting date	21.373

Machine Type





Field Test Report

23.5R25 M3HA+ 2** ECOMEGA E3/L3 TL

Test Report

INSPEC DATE	TIRE POS.	HOURS MONT.	HOURS INSPEC.	HOURS RUNNING	ORIG. T.D. (mm)	T.D. INTER N (mm)	T.D. EXTERN (mm)	PROJECTION TO END (hours)	INFL. (bar)
23/01/2014 FITTING DATE	FL	21.373	21.373	0	29	29	29		0,0
	FR	21.373	21.373	0	29	29	29		0,0
	RL	21.373	21.373	0	29	29	29		0,0
	RR	21.373	21.373	0	29	29	29		0,0
01/03/2016 DEMOUNTED DATE	FL	21.373	26.945	5.572	0	0	0	TEST CONCLUDED	FL
	FR	21.373	26.945	5.572	0	0	0	TEST CONCLUDED	FR
	RL	21.373	26.945	5.572	0	0	0	TEST CONCLUDED	RL
	RR	21.373	26.945	5.572	0	0	0	TEST CONCLUDED	RR

Feedback

TEST SUCCESSFULLY CONCLUDED AT 5.572 HOURS WITH GREAT SATISFACTION FROM CUSTOMER THAT REPLACE WITH NEW ECOMEGA M3HA+.

Target to end

ESTIMATED LIFE AT: TEST CONCLUDED
 DEMOUNTING DATE: 01/03/2016
 TOTAL WORKING HOURS: 5.572