

Field Test Report

23.5R25 ECOMEGA M5UM L5-S 2** TL



LATEST INSPECTION DATE

06/05/2014


2014

COVINI.

Background Info

| | |
|-----------------------|--------------------|
| Customer Reference | CI06639 |
| Country/City | ITALY / CREPELLANO |
| Dimension | 23.5R25 |
| Brand/Type | ECOMEGA M5UM L5-S |
| Operation site | STEEL RECYCLING |
| Machine Producer | LIEBHERR |
| Model | 564 |
| Tires fitting date | 01/07/2014 |
| Hours at fitting date | 15.800 |

Machine Type





Field Test Report

23.5R25 ECOMEGA M5UM L5-S 2** TL

Test Report

| INSPEC DATE | TIRE POS. | HOURS MONT. | HOURS INSPEC. | HOURS RUNNING | ORI G. T.D. (mm) | T.D. INTERN (mm) | T.D. EXTERN (mm) | T.D. AVERAGE (mm) | PROJECTION TO END (hours) | INFL. (bar) |
|-------------|-----------|-------------|---------------|---------------|------------------|------------------|------------------|-------------------|---------------------------|-------------|
| 06/05/2014 | FL | 15.800 | 17.296 | 1.496 | 88 | 53 | 53 | 53 | 3.761 | |
| | FR | 15.800 | 17.296 | 1.496 | 88 | 48 | 48 | 48 | 3.291 | |
| | RL | 15.800 | 17.296 | 1.496 | 88 | 46 | 46 | 46 | 3.134 | |
| | RR | 15.800 | 17.296 | 1.496 | 88 | 53 | 53 | 53 | 3.761 | |

Note

TIRES ARE FILLED WITH POLIURETHANE
MACHINE WORKS IN SCRAP YARD

Target to ent

ESTIMATED LIFE AT THE END OF THE LIFE - FRONT: 3.200 hours
ESTIMATED LIFE AT THE END OF THE LIFE - REAR: 3.700 hours

DEMOUNTING DATE:
TOTAL WORKING HOURS:

FIRST INSPECTION

AVERAGE WORKED HOURS FOR EACH MM: 40 H FRONT
AVERAGE WORKED HOURS FOR EACH MM: 39 H REAR

SECOND INSPECTION

Field Test Report

Conclusion

Photo report

